

METHOD STATEMENT

Scrabbling Floors

Area is cleaned and prepared.

The scrubbling equipment can now be set up

Make sure that there are no obstacles and all cables run free so the process can begin

First the machine is set to the required depth of Latencies to be removed to provide a dry dust free surface

The machine then passes over the sub-floor back and fourth until the process is complete

Tools Required

Scrabbler, Transformer, 110 V Leads, vacuum

RISK ASSESSMENT

Inhalation of dust and frying fragments

To be Supplied

Gloves, Masks and Goggles

Signed:

Position:

Date: