

METHOD STATEMENT

Applying Primer

Area is cleaned and prepared.

The two parts of the D.P.M are then mixed together using an electric whisk

A paint brush is then used to coat the outside perimeter of the floor space

The remaining floor space is then coated with the DPM using a floor roller

The DPM is then given 12 hours to dry and the second coat can then be applied

The two parts of the DPM are mixed together. A paint brush is then used to coat the perimeter

The remaining floor space is now coated using the floor roller in the opposite direction than the first coat.

The DPM is then given 12 hours to dry.

Tools Required

Paint Tray, Paint Brush, Floor Roller, Drill and Whisk

RISK ASSESSMENT

Minimal, as protection provided;

Possible cut from Stanley Knife.

Signed:

Position:

Date: