

METHOD STATEMENT

WELDING SHEET VINYL INSTALLATION

Make sure the Grooves between each joint is cleaned and prepared.

Pre-heat the welding gun.

Ensure that the temperature is correct.

We feed the weld rod into the welder and insert into the groove of the sheet vinyl at one end
Of the joint, after we have finished the welding, allow the weld to cool down.

When the weld is at room temperature we then trim the excess weld off for a smooth
Finish.

10a) Tools Required

2-meter rigid straight edge, Straight and hook bladed knives, Welding equipment and First aid box.

RISK ASSESSMENT

Minimal, as protection provided;

Possible cut from Stanley Knife.

Signed:

Position:

Date: